



Aero Energy

Engine Removal \ Installation Report

Aug 15 , 2018

For



Compressor B train


ESN 481-723 Removed

ESN 481-724 Installed

GE Oracle Project 50010081

Customer Representative:

GE Field Service Representative:



All technical recommendations and information contained in this report are based on GE manuals that have been developed and approved for use with GE engines and parts that have been operated and maintained in accordance with GE technical documentation and recommendations.

Report completed by –



Aero Energy

LM2500 SAC Report

GE has no technical knowledge of, nor obligation for, non GE-approved parts and repairs. Accordingly, this report is not intended to apply to non GE-approved parts and repairs, nor to any parts that may be directly or indirectly affected by non GE-approved parts and repairs.

CONCLUSIONS & RECOMMENDATIONS

The purpose of this visit was to remove engine 481- 723 and install engine 481-724

Outage Data:

Removed engine:

ESN	481 723	Engine Fired Hours	?	Gas	
Model	LM2500 SAC	Engine Fired starts			

Maintenance Data:

WP, SB, SL, PB, PL Performed	Revision/manual reference	Date completed	Comments
WP301 00	GG Assembly replacement	15/8-18	
WP 505 00	GG transfer to/from shipping cont.	15/8-18	

Parts Data

Description	PN Removed		Qty		PN Installed	SN Installed
Ignitor cable			1		9600M37P13	
Ignitors			2		100002494	
Starter gasket			1		100002693	
Starter o-ring			1		J221P222	
Nut			96		9610M50P02	

Open Action Items:

On inspection of exhaust it was seen that on the anti-vibration ring some of the bolts had come loose and began fretting against the flange, customer informed and they shall carry out repair



DETAILS AND DATA

NOTES:

GE \ FieldCore performed this outage in co-operation with JKP Fieldservice and Total platform technicians

Purpose of visit:

The purpose of this visit was to remove engine ESN 481-723 and install engine 481-724.

Work performed:

- Engine removed 481 723 and placed in a trolley
- Package floor cleaned
- Engine lifted up to container deck and placed in the container
- The new engine 481 724 lifted from the container to a trolley outside the enclosure
- The new engine installed
- Inlet plenum floor cleaned
- New gasket on the inlet plenum door
- Found a damage on one of the ignitorcables.Changed it to a new one.
- Two of the attach/clamps on the vent hoses was not properly attached, this was fixed
- Inspection of the exhaust(customer)
- Changed two syntetic oil filters (supply,scavenge)
- VSV calibration/schedule
- HP Recoup calculation



Daily activities:

- 07.8.18 Arrived on site 12.30
Induction course
Had a safety meeting with all the involved personnel for the job.
- 08.8.18 Started with a Toolbox talk.
Began to open the plenum doors. And then with removal of connections to the turbine.
The platform riggers installed the lifting beam inside the enclosure.
The nightshift continued with removal of connections and GG/PT split flange.
- 09.8.18 During nightshift engine removed to transport trolley and lifted further to the container deck. The new engine was taken out of the container and into a trolley next to the enclosure. The old engine installed into container and secured.
Dayshift continued, and lifted in the new engine, and installing of the connections.
The old starter was assembled on the new engine.
- 10.8.18 The last connections finished, and the plenum door closed. Plenum cleaned.
Opened the exhaust duct door, and standby for permit to access the exhaust.
- 11.8.18 The nightshift entered the exhaust for inspection. This was done by the customer.
Nightshift turned over to dayshift.
Standby waiting for permit for PM check.
Two synthetic oil filters changed (supply, scavenge)
- 12.8.18 VSV calibration
PM check finished (customer)
Standby
- 13.8.18 Standby for startup
- 14.8.18 Standby for startup
The engine was cranked at 1700
Startup at 2100, the engine tripped after five minutes on idle (8400 RPM) due to a transmitter fault on the compressor. Entered the enclosure for leak check, no visible leaks found.
Engine started up again, VSV schedule was carried out.
- 15.8.18 HP Recoup calculation
Leaving the platform



Aero Energy

LM2500 SAC Report

Results:



Old engine removed (481-723)



Old engine placed in dolly




New engine (481-724) lowered from upper deck




Aero Energy

LM2500 SAC Report




New engine into enclosure



PT fwd side



Stg 6 LPT nozzles




Loose bolts on Anti vibration ring




Aero Energy

LM2500 SAC Report




Damaged Ignitor cable



Old gasket ,plenum door

VSV SCHEDULE (GREEN) BELLCRANK



Page 1



Aero Energy

LM2500 SAC Report

HP RECOUP ORIFICE SELECTION WORKSHEET					
LM2500 PE, PL, GE, GJ, PJ, GN, GS, PN, PS, PI, and PF MODELS ONLY					
SITE Tyra West		DATE: 15.08.2018		RESET FORM	LOG DATA
ESN: 481 724		MODEL: FE/PL			
Remove steam injection for a data point.					
Fill in the below information for a data point: TARGET DATA POINT BETWEEN 8000 AND 9450 RPM AND ABOVE 40 PSIA P&4					
CURRENT ORIFICE DIA		0.700	Inches	(A)	
INLET TEMPERATURE	(T2)	67.0	Deg F	(1)	
INLET PRESSURE	(P2)	54.6	Psia	(2)	
HP RECOUP PRESSURE	(HPRCP)	74.0	Psia	(3)	
ODP	(P6.3)	23.5	Psia	(4)	
GG SPEED	(NGG)	8890	RPM	(5)	
LPT INLET PRESSURE	(P5.4)	53.7	Psia	(6)	
Corrected Measurements:					
Corrected HPRC Pressure ((HPRCP/Delta) X 14.698)		14.696 * (74.00	/	14.60
14.696 x ((3) / (2)) = (7)		(3)	(2)	=	74.49
Corrected ODP Pressure ((P6.3/Delta) X 14.698)		14.696 * (23.50	/	14.60
14.696 x ((4) / (2)) = (8)		(4)	(2)	=	23.66
Temperature Ratio (SQ RT of Theta)		SqRt of ((67.00	+ 459.67) /	518.67]
SqRt of (((1) + 459.67) / 518.67) = (9)		(1)	=	(9)	1.008
Corrected Gas Generator Speed (NGGR)		(5) / (9) = (10)	8890.00	/	1.01
(5) / (9) = (10)		(5)	(9)	=	8812
HPT Pressure Ratio (P6.3 / P6.4)		(4) / (6) = (11)	23.50	/	53.70
(4) / (6) = (11)		(4)	(6)	=	0.438
4B Bearing Optimization Calculations:					
(7) x 1.3041 = (13)		(7)	74.49	x	1.3041
(7) x 1.3041 = (13)		(7)	74.49	x	1.3041
(8) x 0.55675 = (14)		(8)	23.66	x	0.55675
(8) x 0.55675 = (14)		(8)	23.66	x	0.55675
(10) x -0.074472 = (15)		(10)	8812	x	-0.074472
(10) x -0.074472 = (15)		(10)	8812	x	-0.074472
(11) x -27.856 = (16)		(11)	0.44	x	-27.856
(11) x -27.856 = (16)		(11)	0.44	x	-27.856
Sum Total ((13)+(14)+(15)+(16)) = (17)					24.71
Sum Total ((13)+(14)+(15)+(16)) = (17)					24.71
If (17) is > 30.58 then (18) = (17) - 30.58					0.00
If (17) is < 15.92 then (18) = (17) - 15.92					0.00
Predicted ADJUSTMENT needed to Current Orifice Diameter (Inches)					0.000
(18) / 78 = (20) OR (19) / 78 = (20)					0.000
(18) / 78 = (20) OR (19) / 78 = (20)					0.000
NEW ORIFICE DIAMETER (Inches=					0.700